From: Terry Simpson/ESC/R3/USEPA/US

**Sent:** 2/2/2012 6:16:24 PM

To: KarenD Johnson/R3/USEPA/US@EPA

CC: Cynthia Metzger/ESC/R3/USEPA/US@EPA; Fred Foreman/ESC/R3/USEPA/US@EPA

Subject: Cabot QA/QC

Hi, Karen --

Just wanted to update you on Ft. Meade's QA/QC review of the existing data from Cabot's initial 104e response. I'm attaching a table and two checklists. We are using the checklists to inventory the amount of QC in each data file. This will serve two purposes: 1) to make a determination whether there is enough QC present to validate the data; and 2) to document exactly which QC information is missing and/or needed, should we want to specifically request it from Cabot and their labs. The table documents each file by report title, date, and analyses. It also provides a recommendation on the limited use of the data and cross-references the affected samples.

Please take a look at these and let me know your thoughts. Is there anything that you were expecting to see that isn't in here? Thanks!

## Terry

\*\*\*\*\*\*\*\*\*\*\*\*

Terry Simpson, Regional QA Manager US EPA Region 3 Environmental Science Center 701 Mapes Road Ft. Meade, MD 20755-5350

Voice: 410.305.2739 Fax: 410.305.3095

email: simpson.terry@epa.gov

## **Region 3 QA Website:**

http://www.epa.gov/region03/esc/qa/index.htm

Only four types of organizations need to worry about data quality:

Those that care about their customers, Those that care about profit and loss, Those that care about their employees, and Those that care about their futures.

- Thomas C. Redman (2006)

DIM0051621 DIM0051621